



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8

999 18TH STREET- SUITE 300 DENVER, CO 80202-2466 Phone 800-227-8917 http://www.epa.gov/region08

Ref: 8EPR-SR

June 15, 2006

HECTOR IBANEZ-ORTIZ 5090 FILLMORE ST. DENVER, CO 80216

RE: 5090 FILLMORE ST.

Dear Owner.

As part of the VB/I-70 Superfund Site investigation, we recently took soil samples at your property to find out if there is too much lead or arsenic in your yard. The results show that your property does not require a cleanup. The levels of both lead and arsenic are below our cleanup levels. The soil sampling results for your property are as follows:

ADDRESS: 5090 FILLMORE ST.

EPA Cleanup Levels

hea.I

37 parts per million (ppm)

above 400 ppm

Arsenic

6 ppm

above 70 ppm

This means that your property is not considered by EPA to be part of the VB/I-70 Superfund Site. EPA does not believe that further measures are necessary. You and your family are not at significant risk from arsenic through ordinary contact with soil in your yard while playing, working, gardening, etc. Please note that there may be small areas in your yard, particularly near your house, that may have higher levels of lead due to peeling, external lead-based paint. EPA encourages all owners of older properties to take reasonable precautions regarding lead-based paint.

For further information, please feel free to contact EPA Community Involvement Coordinators Jennifer Chergo at (303) 312-6601 or Patricia Courtney at (303) 312-6631.

Sincerely.

Victor Ketellapper

Remedial Project Manager

The Environmental Protection Agency, Region 8

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-5090-FI-01 Client Project ID: 213001.01 Date Collected: 5/24/06

5/25/06

:

Date Received:

Lab Work Order: 06-3348 06-3348-50 Lab Sample ID:

Sample Matrix: Soil

METALS

Method: SW6010 Pren Method: SW3050

	1100 1111111111111111111111111111111111				
Date Prepared: 6/6/06 Date Analyzed: 6/8/06	Lab File ID: 060806PM Method Blank: MB-10079	Dilution Factor: 1 Lab Fraction ID: 06-3348-50A			
Analytes	CAS Number	Result	LQL Unit	ts	
Arsenic	7440-38-2	6.0	4.0 mg/K	.g	
Lead	7439-92-1	37	5.8 mg/K	(g	

Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Approved

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-5090-FI-02 Client Project ID: 213001.01

Date Collected: 5/24/06
Date Received: 5/25/06

Lab Work Order: 06-3348 Lab Sample ID: 06-3348-51

Sample Matrix: Soil

METALS

Method: SW6010 Prep Method: SW3050

Date Prepared: 6/6/06 Date Analyzed: 6/8/06	Lab File ID: 060806PM Method Blank: MB-10079	Dilution Factor: 1 Lab Fraction ID: 06-3348-51A		
Analytes	CAS Number	Result	LQL	Units
Arsenic	7440-38-2	4.5	3.9	mg/Kg
Lead	7439- 9 2-1	42	5.7	mg/Kg

MB Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

 -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL. Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 6/9/06

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-5090-FI-03 Client Project ID: 213001.01

5/24/06

Lab Work Order: 06-3348
Lab Sample ID: 06-3348-52

Sample Matrix: Soil

Date Received: 5/25/06

Method: SW6010

Date Collected:

METALS

Prep Method: SW3050

Dilution Factor: Date Prepared: 6/6/06 Lab File ID: 060806PM Date Analyzed: 6/8/06 Method Blank: MB-10079 Lab Fraction ID: 06-3348-52A **Analytes** CAS Number Result LQL Units Arsenic 7440-38-2 5.0 mg/Kg 33 7439-92-1 5.6 mg/Kg Lead

> ///D Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.


Approved

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 6/9/06





UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
Victor Ketellapper
Phone 800-227-8917
http://www.epa.gov/region08

CONSENTIMIENTO PARA ENTRAR EN LA PROPIEDAD

Nombre del Dueño de la Propiedad: Hector Ibanez-Ortiz (o actual propietario)

Dirección de la Propiedad: 5090 Fillmore St.

Propiedad ID: 6996

Permitiré al personal de la Agencia de Protección del Medio Ambiente de los Estados Unidos(EPA) y a sus representantes autorizados entrar y tener acceso continuo a la propiedad arriba citada con el propósito de tomar muestras de suelo en el lugar.

Yo entiendo que estas acciones son adelantadas por EPA como parte de sus responsabilidades, de acuerdo con las disposiciones de la Respuesta Ecológica Integral, Ley de Responsabilidades y Compensaciones (Comprehensive Environmental Response, Compensation and Liability Act - Superfund) 42 U.S.C. s. 9601, et seq.

Nombre y apellidos

303 308 0 780

Número de Teléfono

Firma

Fecha